



PROPRIETARY NOTICE: THIS DRAWING AND ALL INFORMATION THEREON IS THE PROPERTY OF COTTA, LLC.  
THIS DRAWING IS NOT TO BE COPIED OR USED FOR THE PURPOSE OF MANUFACTURING EXCEPT BY WRITTEN  
CONSENT OF COTTA, LLC.  
TORSIONAL VIBRATIONS EXIST IN ALL ROTATING SYSTEMS. IT IS THE SOLE RESPONSIBILITY OF THE EQUIPMENT  
MANUFACTURER OR ASSEMBLER TO INSURE THAT NO DAMAGING CRITICALS FALL IN THE OPERATING RANGE OF THE SYSTEM.


ENGINEERING CHANGE NOTICES				
LTR	DESCRIPTION	ECN	DATE	BY

THE FOLLOWING PARTS ARE NOT SHOWN & SHIPPED LOOSE:  
ITEM 4: 02H9625A (1) HOSE ASSEMBLY  
ITEM 28: 80BX137 (1) NUT  
ITEM 32: 80DX119 (1) LOCKWASHER  
ITEM 44: 80JX351 (1) GREASE FITTING  
ITEM 45: 80JX676 (1) BULKHEAD ADAPTER  
ITEM 46: 80JX677 (1) ELBOW  
ITEM 48: 80MX101 (2) WOODRUFF KEY



NOT FOR PRODUCTION

UNLESS OTHERWISE NOTED  
1. USE STANDARD CAPSCREW TIGHTENING TORQUES  
APPLYING LOCTITE 242 OR EQUIVALENT.

TEST PER SPECIFICATION DE-9905. REFERENCES: DE-0801, TB01-101, DE-0102				REVISION DATE 30-MAR-23		
MODEL  S1521		 <b>Cotta</b> 1301 PRINCE HALL DRIVE BELOIT, WI 53511		OVERSPEED GEARBOX		
DRAWN TAP	DATE 30-MAR-23					PART NAME
CHECKED -	DATE -					
APPROVED	DATE					
SCALE HALF	SHEET 1 OF 1					PART NUMBER
DIMENSIONS ARE IN INCHES AND REFERENCE UNLESS TOLERANCED				S1521-22		